

BELLER'S LLC

email-

Workfile ID: PartsShare:

ffb510f3 6tDfpL

website-www.bellersauto.com mikebellers@gmail.com

Federal ID: State ID:

161589940 7088448

4783 STATE ROUTE 410, CASTORLAND, NY 13620

Phone: (315) 376-2671 FAX: (315) 376-8570

Preliminary Estimate

Customer: Copenhagen, Village of

Job Number:

Written By: Michael Beller

Insured:

Copenhagen, Village of

Policy #:

Claim #:

Type of Loss:

Date of Loss:

Days to Repair:

Point of Impact: 01 Right Front

Owner:

Copenhagen, Village of

(315) 688-4229 Cell

Inspection Location:

Insurance Company:

BELLER'S LLC

4783 STATE ROUTE 410 CASTORLAND, NY 13620

Repair Facility

(315) 376-2671 Business

VEHICLE

2021 FORD Super Duty F-250 w/Single Rear Wheels XL Supercab 4WD w/6.75' Box 4D SHORT 8-6.2L Flex Fuel Sequential MPI red

VIN:

1FT7X2B60MED48882

Interior Color:

Mileage In:

Vehicle Out:

License:

Exterior Color:

red

Mileage Out:

State:

NY

Production Date:

Condition:

Excellent

3,588

Job #:

TRANSMISSION

Automatic Transmission

4 Wheel Drive

POWER

Power Steering

Power Brakes

DECOR

Dual Mirrors

Tinted Glass

Overhead Console

CONVENIENCE Air Conditioning

Intermittent Wipers

Tilt Wheel

Message Center

Steering Wheel Touch Controls

Telescopic Wheel

Backup Camera

Remote Starter

RADIO

AM Radio

FM Radio

Stereo

Search/Seek

SAFETY

Drivers Side Air Bag

Passenger Air Bag

Anti-Lock Brakes (4)

4 Wheel Disc Brakes

Traction Control

Stability Control

Front Side Impact Air Bags

Head/Curtain Air Bags

Hands Free Device

SEATS

Reclining/Lounge Seats

WHEELS

Styled Steel Wheels

PAINT

Clear Coat Paint

OTHER

California Emissions

TRUCK

Rear Step Bumper

Trailer Hitch

Preliminary Estimate

Customer: Copenhagen, Village of

Job Number:

2021 FORD Super Duty F-250 w/Single Rear Wheels XL Supercab 4WD w/6.75' Box 4D SHORT 8-6.2L Flex Fuel Sequential MPI red

Line	Oper	Description	Part Number	Qty	Extended Price \$	Labor	Paint
1	FRONT BUMPER						
2		O/H front bumper				3.7	
3	Repl	Bumper painted w/o fog lamps	LC3Z17757AA	1	815.58	Incl.	2.1
4		Add for Clear Coat					0.8
5	Repl	RT Mount plate	LC3Z17B984A	1	93.33	Incl.	0.0
6	Repl	RT Mount bracket	HC3Z17B836C	1	21.99	0.2	
7	Repl	RT Outer bracket	LC3Z17754A	1	31.55	Incl.	
8	R&I	Step pad				Incl.	
			SUBTOTALS		962.45	3.9	2.9

ESTIMATE TOTALS

Category	Basis		Rate	Cost \$	
Parts				962.45	
Body Labor	3.9 hrs	@	\$ 50.00 /hr	195.00	
Paint Labor	2.9 hrs	@	\$ 50.00 /hr	145.00	
Paint Supplies	2.9 hrs	@	\$ 30.00 /hr	87.00	
Body Supplies	0.2 hrs	@	\$ 6.00 /hr	1.20	
Subtotal			,	1,390.65	
Grand Total				1,390.65	
Deductible				0.00	
CUSTOMER PAY				0.00	
INSURANCE PAY				1,390.65	

MyPriceLink Estimate ID / Quote ID:

880462971027857408 / 94774870

ANY PERSON WHO KNOWINGLY AND WITH INTENT TO DEFRAUD ANY INSURANCE COMPANY OR OTHER PERSON FILES AN APPLICATION FOR COMMERCIAL INSURANCE OR A STATEMENT OF CLAIM FOR ANY COMMERCIAL OR PERSONAL INSURANCE BENEFITS CONTAINING ANY MATERIALLY FALSE INFORMATION, OR CONCEALS FOR THE PURPOSE OF MISLEADING, INFORMATION CONCERNING ANY FACT MATERIAL THERETO, AND ANY PERSON WHO, IN CONNECTION WITH SUCH APPLICATION OR CLAIM, KNOWINGLY MAKES OR KNOWINGLY ASSISTS, ABETS, SOLICITS OR CONSPIRES WITH ANOTHER TO MAKE A FALSE REPORT OF THE THEFT, DESTRUCTION, DAMAGE OR CONVERSION OF ANY MOTOR VEHICLE TO A LAW ENFORCEMENT AGENCY, THE DEPARTMENT OF MOTOR VEHICLES OR AN INSURANCE COMPANY, COMMITS A FRAUDULENT INSURANCE ACT, WHICH IS A CRIME, AND SHALL ALSO BE SUBJECT TO A CIVIL PENALTY NOT TO EXCEED FIVE THOUSAND DOLLARS AND THE VALUE OF THE SUBJECT MOTOR VEHICLE OR STATED CLAIM FOR EACH VIOLATION.

You are entitled to the return of all replaced parts, except warranty and exchange parts, but you must ask for them in writing before any work is done. If you authorize work by phone, the shop must keep any replaced parts, and make them available when you pick up the vehicle.